



DRIVEN BY RACING

Clerk of the Course Decision

Circuit:	Brands Hatch Indy	Date:	20-10-2024
From:	Paul Levitt (252266)	Clerk of the Course	
To:	Joseph Wiggin	Competition No:	41
Race Title:	BRSCC Mazda MX-5 SuperCup Championship - Race 17	ASN:	Motorsport UK
Time of Issue:	17:58	Licence No:	246613

Having received a report from the Championship Eligibility Scrutineer (reference 2001024 MJG41). As per Championship Regulation 5.2.2. Driver of car 41 failed to present a previously sealed engine with seal number 000062 sealing record SC411603EN. Having interviewed Driver of car 41 it became apparent that the required parts were only fully confirmed on the Thursday before the event (17/10/24) by email. The part in question had been sold to another party. Driver of Car 41 was advised that he must arrange for the required part to be made available for inspection within the next 14 days and must agree an appointment with the championship eligibility scrutineer and at his approval within the next 24 hours. All expenses are to be covered by the competitor as per championship regulation 5.2.2.C

You are reminded of your right of appeal. Any penalties applied will be recorded by Motorsport UK in accordance with Motorsport UK Regulation C 2.1.4

Signed:		Date:	20-10-2024
Clerk of the Course	Paul Levitt (252266)	Time:	17:58

I being the Entrant / Driver of Car No: **41** acknowledge receipt of the above decision

The competitor was advised at the time stated above that this form would be emailed to them and that the appeal process would then follow the procedure laid down in the current Motorsport UK Yearbook.

Fines or Costs must be paid to Motorsport UK within 7 days of being imposed. Any delay in making payment may result in suspension of licence for the period during which the amount remains unpaid, beyond the said period of 7 days. To pay, call Motorsport UK on 01753 765000 (option 2).