

Clerk of the Course Decision

Circuit:	Snetterton 300	Date:	16-10-2022
From:	Paul Levitt (252266)	Clerk of the Course	
То:	Ali Bray	Competition No:	14
Race Title:	BRSCC Mazda MX-5 SuperCup - Qualifying	Licence No:	250028
Time of Issue:	08:05		

Following investigations, I find that you are guilty of contravening the following Championship Regulation(s):

2.2 Prohibited Modifications

Brief Details:

Car 14s engine was sealed following qualifying.

Car 14 was found by the scruitineers to not comply with the standard Cam timing after the race (RACE 3). Scrutineer completed non compliance report.

Accordingly, under Motorsport UK Regulation G 5.3, I hereby order that you receive the following:

Disqualified from the results of qualifying or practice.

You are reminded of your right of appeal. Any penalties applied will be recorded by Motorsport UK in accordance with Motorsport UK Regulation C 2.1.4

Signed:		Date:	16-10-2022
Clerk of the Course	Paul Levitt (252266)	Time:	08:05

I being the Entrant / Driver of Car No: 14 acknowledge receipt of the above decision

The competitor was advised at the time stated above that this form would be emailed to them and that the appeal process would then follow the procedure laid down in the current Motorsport UK Yearbook.

Fines or Costs must be paid to Motorsport UK within 7 days of being imposed. Any delay in making payment may result in suspension of licence for the period during which the amount remains unpaid, beyond the said period of 7 days. To pay, call Motorsport UK on 01753 765000 (option 2).